

Report ID: 16,866,110 Version: 5 Created: 07 May 2018

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A	
Year:	,006 Registration: JRP285 Reg Expiry: 18 Dec 2017				Engine					
WoF Expiry:	24 Sep 2018	Odometer:	332,996 Kms	Good No:	16866110	Oil level	~			
VIN:	KMHSH81WR6U03410	Next Service:	336000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	~			
Key:		-0	P P	-01-	Р	Radiator / Hoses (visual)	~			
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent						Transmission				
						Operation	~			
						Noise	~			
						Clutch			~	
						CV joints	~			
* = decals SDPTSC 919						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S P S P S						Performance	~			
Dedution		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)	
Small cracks on paint work bonnet ,								mm		
						Right front		4	mm	
						Left rear			mm	
Conditions During Body Inspection: Dry						Right rear			mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats Average						Head lights	~			
	Good					Tail lights	~			
Carpets	Guu					Indicators	~			
Panels	Average					Dashboard warning lights	~			
	, Good					Wipers (front & rear)		~		
Dashboa	rd Good					Window winder FL	~			
	1					Window winder FR	~			
General Comments						Window winder RL	~			
Rear wiper not working						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		1	
Road Conditions During Test Drive: Dry						Central locking	~			
			у			Remote locking	~			
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)	. 		~	
Evidence of Cam Belt Replacement: Yes Kms: 292,570						Reversing camera			~	
Inspected by: Donovan Matara Date: 07 May 2018										

I have read and understood this condition guide.

Name:

Signature: