

Report ID: 16,866,943 Version: 1 Created: 05 Oct 2017

Make:	Toyota	Model:	Granvia	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,996	Registration:	ERH892	Reg Expiry:	29 Oct 2017	Engine			
WoF Expiry:		Odometer:	537,396 Kms	Good No:	16866943	Oil level	~		
VIN:	7A8H6320707010138	Next Service:	250000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S P SC		S		S D	Performance	V		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission			
						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
S D S D S D S D S D S D S D S D S D S D						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
LH door mirror scratched ,LR tail light cracked ,LR tail light on tail gate cracked,badge missing on the tail gate						Tyres (lowest observed tread depth of tyres)			
,crack in the windscreen ,						Left front		7	mm
						Right front		7 mm	
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments wear and tear,minor stains,						Electrical / Accessories			
Seats	wear and t	ear,minor stains	,			Head lights	~		
Carpote	wear and	ear,minor stains	,			Tail lights		~	
Carpets	-					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa	ru –					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u> T-Belt light is on ,						Window winder RL			~
I-Beit light	is on ,					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking			~
						Sat. Nav. (basic test only)			~
	ог сапт вен керіас	ement: N	lo	Kms:		Reversing camera			~
Inspecte	d by: Donovan Matar	Date: 05 Oct 2017							
I have read and understood this condition guide. Name:									