

Report ID: 16,869,732 Version: 1 Created: 04 Oct 2017

Make:	Holden	Model:	Vectra	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,002	Registration:	FMC857	Reg Expiry:	05 Nov 2017	Engine	I	<u> </u>	1
WoF Expiry:	02 Dec 2017	Odometer:	250,529 Kms	Good No:	16869732	Oil level	~		
VIN:	W0L0JBF1911195193	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismontiad as						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S D SC	-0	S D S D SC		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S P SC			The	E SSC	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+	PT	Clutch			~
P = pin dent	Ho	KI			JUII —	CV joints	~		
* = decals	SCPSC PSC			AL-	ELP IS				
SC = stone chips						Wheel bearings Brakes	~		
W = significant scuffs S SC S P SC S P SC S P SC									1
Noto come defecte ⁰ blamiches may not be displayed in the dispran							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<i>с</i> .	Ļ
Boot spoiler scratched and cracked ,roof paint faded,						Tyres (lowest observed tread depth of tyres)			
						Left front 1			mm
						Right front			mm
						Left rear		2 mm	
Conditions During Body Inspection: Dry						Right rear	2 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & Under bor	inet inspectio	<u>on comments</u>			Suspension	1	-	
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments wear and tear, minor stains,						Electrical / Accessories			
Seats	wear and	lear, minor stains	1			Head lights	~		
Carpets	wear and t	ear,minor stains,				Tail lights	~		
Carpets					Indicators	~			
Panels	Average					Dashboard warning lights	~		
Dashboa	stereo face	e missing ,				Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL	~		
2 front tyres need replacing, stereo face missing , passengers front seat broken ,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 04 Oct 2017									
I have read and understood this condition guide. Name:									