

Report ID: 16,872,110 Version: 1 Created: 06 Oct 2017

| Make:  | Holden   | Model:            | Astra                  | Body Style:        | Hatchback    | ]      |  | Pass                  | Fail     | N/A |  |
|--|--|-------------------|------------------------|--------------------|--------------|--------|--|-----------------------|----------|-----|--|
| Year:  | 2,004 Registration: CKD313 Reg Expiry: 01 Jul 2018 |                   |                        |                    |              | Engine |  |                       | •        |     |  |
| WoF Expiry:  | 01 Dec 2017  | Odometer:         | 159,931 Kms            | Good No:           | 16872110     |        | Oil level                                    | ~                     |          |     |  |
| VIN:   | W0L0TGF485G006712                                  | Next Service:     | 0                      | Service Histor     | <b>y:</b> No |        | Smoke & fumes                                | ~                     |          |     |  |
|  |  |                   |                        |                    |              |        | Performance                                  | ~                     |          |     |  |
| Note: This report is not a warranty<br>This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or   |  |                   |                        |                    |              | H      | Noise  | ~                     |          |     |  |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |  |                   |                        |                    |              |        | Cooling System                               |                       |          |     |  |
| a full mechan  | ical inspection prior to                           | purchase and t    | his can be arranged fo | or an additional o | harge.       |        | Coolant condition                            | ~                     |          |     |  |
|  |  |                   |                        |                    |              | ור     | Performance                                  | ~                     |          |     |  |
| Key:   | SD   | -0                | SD SD                  | -161-              | s            |        | Radiator / Hoses (visual)                    | v                     |          |     |  |
| S = scratch  |  |                   |                        |                    |              |        | Transmission                                 | •                     |          |     |  |
| D = dent<br>B = sust SPSC SD SD  |  |                   |                        |                    |              |        | Operation                                    | ~                     |          |     |  |
|  |  |                   |                        |                    |              |        | Noise  | •<br>•                |          |     |  |
| PT = paint defect<br>C = crack   |  |                   |                        |                    |              |        | Clutch                                       | •                     |          | ~   |  |
| P = pin dent   |  |                   |                        |                    |              |        | CV joints                                    | ~                     |          |     |  |
| * = decals SDSC PIP  |  |                   |                        |                    |              |        | Wheel bearings                               |                       |          |     |  |
| SC = stone chips   |  |                   |                        |                    |              |        |  | ~                     |          |     |  |
| W = significant scuffs SC SD SD SD SD SD   |  |                   |                        |                    |              |        | Brakes<br>Performance                        |                       |          |     |  |
| Nata como doforte 9 blamichos may not bo displayed in the diagram  |  |                   |                        |                    |              |        |  | <b>v</b>              |          |     |  |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram  |  |                   |                        |                    |              |        | Hand Brake                                   | <ul> <li>✓</li> </ul> | <u> </u> | Ļ   |  |
|  |  |                   |                        |                    |              |        | Tyres (lowest observed tread depth of tyres) |                       |          |     |  |
|  |  |                   |                        |                    |              |        | Left front                                   | 4                     | 4        | mm  |  |
|  |  |                   |                        |                    |              |        | Right front                                  | 4                     | 4        | mm  |  |
|  |  |                   |                        |                    |              |        | Left rear                                    | :                     | 3        | mm  |  |
| Conditions During Body Inspection: Dry   |  |                   |                        |                    |              |        | Right rear 3 mi                              |                       |          | mm  |  |
|  |  |                   |                        |                    |              | ור     | Spare Yes                                    |                       |          |     |  |
| Under Carriage & Under Bonnet Inspection Comments  |  |                   |                        |                    |              |        | Suspension                                   |                       |          |     |  |
| Minor oil le   | ak ,   |                   |                        |                    |              |        | Suspension performance                       | ~                     |          |     |  |
|  |  |                   |                        |                    |              |        | Steering performance                         | ~                     |          |     |  |
|  |  |                   |                        |                    |              |        | Shock absorbers                              | ~                     |          |     |  |
|  |  |                   |                        |                    |              |        | Air Conditioning / Heater                    |                       | -        | _   |  |
|  |  |                   |                        |                    |              |        | Operation                                    |                       | ~        |     |  |
| Interior Comments drivers seat ripped, wear and tear, minor stains ,   |  |                   |                        |                    |              |        | Electrical / Accessories                     |                       |          |     |  |
| Seats  | drivers sea  | it ripped,wear ar | id tear,minor stains , |                    |              |        | Head lights                                  | ~                     |          |     |  |
|  | wear and t   | ear,minor stains  | ,                      |                    |              |        | Tail lights                                  | ~                     |          |     |  |
| Carpets  |  |                   |                        |                    |              |        | Indicators                                   | ~                     |          |     |  |
| Panels   | Average  |                   |                        |                    | 1            |        | Dashboard warning lights                     | ~                     |          |     |  |
|  | stereo mis   | sina .            |                        |                    |              |        | Wipers (front & rear)                        | ~                     |          |     |  |
| Dashboa  | rd   | y /               |                        |                    |              |        | Window winder FL                             | ~                     |          |     |  |
|  | ·  |                   |                        |                    |              | ļ      | Window winder FR                             | ~                     |          |     |  |
| General Comments   |  |                   |                        |                    |              |        | Window winder RL                             | ~                     |          |     |  |
| Engine light is on ,rear view mirror broken ,  |  |                   |                        |                    |              |        | Window winder RR                             | ~                     |          |     |  |
|  |  |                   |                        |                    |              |        | Rear view mirrors                            | ~                     |          |     |  |
|  |  |                   |                        |                    |              |        | Radio (basic test only)                      |                       |          | ~   |  |
|  |  |                   |                        |                    |              |        | CD (basic test only)                         |                       |          | ~   |  |
|  |  |                   |                        |                    |              |        | Number of keys                               | 1                     | I        | L . |  |
| Pood Conditions During Test Driver   |  |                   |                        |                    |              | ן ך    | Central locking                              | ·<br>·                |          |     |  |
| Road Conditions During Test Drive: Dry   |  |                   |                        |                    |              | ]      | Remote locking                               | ~                     |          |     |  |
| Engine Timing Mechanism: Cambelt   |  |                   |                        |                    |              | ון     | Sat. Nav. (basic test only)                  | -                     |          | ~   |  |
| Evidence of Cam Belt Replacement: No Kms:  |  |                   |                        |                    |              |        | Reversing camera                             |                       |          | ~   |  |
|  | -1   | ľ                 |                        |                    |              |        | neversing camera                             |                       |          |     |  |
| Inspecte   | Inspected by: Donovan Matara Date: 06 Oct 2017     |                   |                        |                    |              |        |  |                       |          |     |  |
|  |  |                   |                        |                    |              |        |  |                       |          |     |  |

I have read and understood this condition guide.

Name: .....

Signature: .....