

Report ID: 16,873,845 Version: 1 Created: 09 Oct 2017

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,999	Registration:	CLG984	Reg Expiry:	03 Oct 2017	Engine			•
WoF Expiry:	11 Oct 2017	Odometer:	248,053 Kms	Good No:	16873845	Oil level	~		
VIN:	JHMRA3880XC204754	Next Service:		Service Histor	y: No	Smoke & fumes	r		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	w w	-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent B = mut						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent	Ho					CV joints	~		~
* = decals	S PT SC W P			AL-		Wheel bearings			
SC = stone chips							~		
W = significant scuffs PT S D R S W SC W						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Badge missing from the back,clear coat coming off the bonnet						Tyres (lowest observed tread depth of tyres)			
						Left front	:	3	mm
						Right front	:	3	mm
						Left rear	:	5	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	stain drive	r side				Tail lights	~		
Carpets	Stant anve	1 Sluc				Indicators	V		
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL		~	
	I					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	-		~
						Number of keys	1		•
							1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking			~
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
			10			Reversing camera			~
Inspected by: Donovan Matara Date: 09 Oct 2017									

I have read and understood this condition guide.

Name:

Signature: