

Report ID: 16,877,854 Version: 1 Created: 09 Oct 2017

Make:	Nissan	Model:	Bluebird	Body Style:	Sedan		Pass	Fail	N/A
Year:	1,992	Registration:	UX2725	Reg Expiry:	19 Sep 2017	Engine			
WoF Expiry:	08 Mar 2018	Odometer:	214,272 Kms	Good No:	16877854	Oil level	~		
VIN:	7A8DH1E0796091918	Next Service:	219000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	
						Performance	~		
Key:	sc	-0	S S	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals PT SC PIP						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC S D S D S D S W						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Clearcoat is coming off. Both L&R mirrors are damaged. Loose wires in boot. Damage on RR weatherstrip.						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres)		
Stonechips on windscreen. Headlamps need buffing. Radio not working, no aerial?. Wear on RF seat. Marks						Left front 3 mm			mm
on LF seat. LH sunvisor missing, RH damaged.						Right front		3	mm
						Left rear		6 m	
Conditions During Body Inspection: Drv						Right rear	e	-	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Battery not secure. Engine has oil leaks. Coolant additve concentration below manufacturers recommended level , contains only water no additive, suggest coolant change and flush. Repairs have been done to chassis rails underneath floor on both sides. RH sill damaged.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~	-	
General Comments					Window winder RL	~			
Trim inside RH mirror missing. All CV boots are torn. Play in rear swaybar bushes.						Window winder RR	~		
Drives ok.						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Roger King Date: 09 Oct 2017									

I have read and understood this condition guide.

Name:

Signature: