

Basic Vehicle Condition Guide

Report ID: 16,879,223

Version:


Created: 11 Oct 2017

Pass Fail N/A

Make: Model: Hilux **Body Style:** Utility Toyota Year: Registration: FUB135 Reg Expiry: 23 Dec 2017 2,011 WoF Expiry: **Odometer:** 19 Apr 2018 **Good No:** 16879223 173,586 Kms VIN: MR0EZ12G204010728 Next Service: **Service History:** 180000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RF bumper insert missing Left rear lens cracked

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Dirty

Flat battery

Interior Comments			
Seats	RF hole. stains		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Inspected by:

Drives OK

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Engine			
Oil level	~		
Smoke & fumes	V V		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission		!	
Operation	~		
Noise	V		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	s)
Left front	(5	mm
Right front	6		mm
Left rear			mm
Right rear	7 mm		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	\(\times \) \(\t		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

Stuart Melbourne I have read and understood this condition guide.

Name:

Signature:

11 Oct 2017

1

Reversing camera