

Basic Vehicle Condition Guide

Report ID: 16,879,425

Version: 1

Engine

Oil level

Noise

Smoke & fumes

Performance

Created: 16 Oct 2017

Pass

~


Fail

N/A

Make: Model: Holden Viva **Body Style:** Hatchback Year: 2,006 Registration: DKG596 Reg Expiry: 27 Jan 2018 **WoF Expiry: Odometer:** 17 May 2018 **Good No:** 16879425 88,186 Kms VIN: KL3NA48BJ6K340322 **Next Service: Service History:** 101000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	wear and tear,minor stains ,	
Carpets	wear and tear,minor stains ,	
Panels	Good	
Dashboard	Good	

General Comments

Inspected by:

Does have a starting fault,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

\(\times \)		
V V V		
V V		
V		
v		
~		
1		
		~
~		
~		
~		
~		
d deptl	of tyr	es)
	7	mm
	7	mm
6		mm
6		mm
Ye		
-		
~		
~		
~		
	1	-1
	~	
~		
~		
~		
~		
~		1
~		
~		1
~		
~		+
~		1
~		
1	-	
~		T
~		+
		\ <u>\</u>
		\ <u>\</u>
17		
	V depth	V

I have read and understood this condition guide.

Donovan Matara

Name:

Signature: