

Report ID: 16,881,638 Version: 2 Created: 10 Oct 2017

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	KRQ424	Reg Expiry:	21 Oct 2017	Engine			L
WoF Expiry:	04 Oct 2018	Odometer:	153,921 Kms	Good No:	16881638	Oil level	~		
VIN:	KMHST81XSEU344603	Next Service:	155000	Service Histor	V: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		for and milaana	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SDSC	-0	SP SP SC		s sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	HIL S	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack					PT SC	Clutch	-		~
P = pin dent	HID				74 <u>11</u>	CV joints	~		-
* = decals	ssc 919			The	ELL SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
					Left front 5 mm				
						Right front	5		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5		 mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	wear and t	tear,minor stains	1			Head lights	~		
						Tail lights	~		
Carpets	wear and t	tear,minor stains	,			Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	<i>v</i>		
						Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Donovan Matara Date: 10 Oct 2017									

I have read and understood this condition guide.

Name:

Signature: