

Report ID: 16,884,120 Version: 1 18 Oct 2017 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,010	Registration:	FRF891	Reg Expiry:	15 Nov 2017	Engine			
WoF Expiry:	04 Nov 2017	Odometer:	251,507 Kms	Good No:	16884120	Oil level	~		
VIN:	JM0GH105200211068	Next Service:	250000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	SP SP		<u>sw</u>	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S P SC			715	HILLS	Operation	~		
PT = paint defe	ect NP			$\left(\left \right\rangle \right)$		Noise	~		
C = crack					R SC	Clutch			~
P = pin dent	-110				세비	CV joints	~		-
* = decals	ssc 919			- Jul	ELD's	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S W S SC S						Performance	~		
Dealerteen	<u></u>	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
	pection Comments			, ,	, ,	Tyres (lowest observed treat	-	of tvre	s)
Spider rust on the roof ,									mm
						Right front			mm
						Left rear		+ 1	mm
Conditions Duving Pody Inspection D						Right rear		+ 1	 mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	wear and t	ear,minor stains	,			Head lights	~		
50005						Tail lights	~		
Carpets	wear and t	ear,minor stains	,			Indicators	~		
Banolo	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL	~		
						Window winder FR	~		
<u>Gen</u> eral (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Drv						Central locking			
Road Con	unions During Test	Dive:	Dry			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									•
Inspected by: Donovan Matara Date: 18 Oct 2017									

I have read and understood this condition guide.

Name:

Signature: