

Report ID: 16,887,320 Version: 1 Created: 12 Oct 2017

Make:	Fiat	Model:	Ducato	Body Style:	Van		Pass	Fail	N/A
Year:	2,016	Registration:	KBC499	Reg Expiry:	29 Aug 2017	Engine	1		
WoF Expiry:		Odometer:	190,813 Kms	Good No:	16887320	Oil level	~		
VIN:	ZFA25000002A16956	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	hoon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	w GlE			The	BID DCW	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+		Clutch	•		~
P = pin dent	Ho					CV joints			~
* = decals	sc pp			AL-	ENR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs									Τ
		Noto: con	a defects & blomisher		laved in the diagram		~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Large crack front screen new screen required.						Tyres (lowest observed tread depth of tyres)			
						Left front		3	mm
						Right front		3	mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	metinspectic	<u>on comments</u>			Suspension			
Good.						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	2		
Deal-I-	Good					Wipers (front & rear)	2		
Dashboa	ird					Window winder FL	<		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Runs well.						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
L							1		
Inspected by: Brian Hill Date: 12 Oct 2									
I have read	and understood th	is condition o	juide. Name:			Signature:			