

Basic Vehicle Condition Guide

Report ID: 16,888,943


Version: 1

Created: 30 Oct 2017

Make: Model: Mazda Atenza **Body Style:** Sedan Year: 2,005 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 13 Oct 2018 126,683 Kms 16888943 VIN: 7AT0C139X17401479 **Next Service: Service History:** 136680

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 16 Oct 2017

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	\(\times \)			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	<i>V</i>			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes	l			
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	6	.0	mm	
Right front	6.0		mm	
Left rear	6.0		mm	
Right rear	6.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	<i>V</i>			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	v v			
Wipers (front & rear)	<i>V</i>			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			'	

I have read and understood this condition guide.

Name:

Signature: