

Basic Vehicle Condition Guide

Report ID: 16,889,276

Version: 1


Created: 13 Oct 2017

Fail N/A

Make: Model: Landcruiser Prado **Body Style:** SUV Toyota Year: Registration: FYM887 Reg Expiry: 2,011 23 Jun 2017 WoF Expiry: **Odometer:** 04 Jul 2017 **Good No:** 16889276 178,787 Kms VIN: **Next Service:** JTEBH3FJ20K051518 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

F bumper insert missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Dirty

Interior Comments		
Seats	Average	
Carpets	Poor	
Panels	Average	
Dashboard	Good	

General Comments

Diesel particle light on T belt light on

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Name:

Engine			
Oil level	~		
Smoke & fumes	>		
Performance	V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			ı
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front		8	mm
Right front	8 mm		
Left rear	8 mm		
Right rear	8 mm		
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			•
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)	V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	>		
Remote locking	>		
Sat Nay (basic test only)			1

Reversing camera

13 Oct 2017

Signature:

I have read and	understood this	condition guide.

Stuart Melbourne