

## **Basic Vehicle Condition Guide**

Report ID: 16,889,442

Version:

Engine

Oil level

Created: 19 Oct 2017

Pass


N/A

Fail

Make: Model: **Body Style:** Utility Ford Ranger Year: Registration: **Reg Expiry:** 2,011 FZP426 30 Sep 2018 WoF Expiry: **Odometer: Good No:** 21 Oct 2018 80,479 Kms 16889442 VIN: **Next Service: Service History:** MNALSBE10BW95425 87;000 Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>	
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

**General Comments** 

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

Smoke & fumes 1 Performance / Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch / CV joints 1 Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 8.2 Left rear 6.8 mm Right rear  $\mathsf{mm}$ 8.5 Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR ~ Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 3 Central locking Remote locking Sat. Nav. (basic test only) Reversing camera

Signature: .....

19 Oct 2017 Inspected by: lan Dunn Date:

Name: .....