

Report ID: 16,889,457 Version: 1 19 Oct 2017 Created:

| Make: | Ford | Model: | Ranger | Body Style: | Utility | | Pass | Fail | N/A |
|--|--------------------------|---------------|------------------------|---------------------|-------------|-------------------------------|----------|---------|---------|
| Year: | 2,011 | Registration: | FZP425 | Reg Expiry: | 30 Sep 2018 | Engine | | | L |
| WoF Expiry: | 21 Sep 2018 | Odometer: | 90,946 Kms | Good No: | 16889457 | Oil level | ~ | | |
| VIN: | MNALSBE10BW94902 | Next Service: | | Service Histor | | Smoke & fumes | ~ | | |
| | | | 57,000 | | | Performance | ~ | | |
| | port is not a warranty | | с I I | | 1 B AL | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| | ical inspection prior to | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | sc | -0 | SC | | PT SC | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | scw 6/6 | | | The | | Operation | ~ | | |
| R = rust PT = paint def | | | | \prod | JHIH | Noise | ~ | | |
| C = crack | | | | $+ \mathbf{\nabla}$ | R SC | Clutch | ~ | | |
| P = pin dent | | | | | 세비 | CV joints | • | | ~ |
| * = decals | sc 916 | | | The | S P SC | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S S S S S S S S S S S S S S S S S S | | | | | | Performance | ~ | | |
| | | Note: son | ne defects & blemishes | may not be disp | | Hand Brake | ~ | | |
| Body inspection Comments | | | | | | Tyres (lowest observed tread | - | of tyre | ا مر |
| Left side sill dents | | | | | | Left front 8.3 mm | | | |
| | | | | | | Right front | 0. 7. | | mm |
| | | | | | | Left rear | 7. | - | mm |
| Conditions During Body Inspection: | | | | | | Right rear | | | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear 7.4 mm Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | - | • | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 3 | | L |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | <i>v</i> | | |
| Road Conditions During Test Drive: Wet | | | | | | Remote locking | - | | ~ |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: No Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspecte | d by: Ian Dunn | | | | | Date: 19 Oct 20 | 17 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: