

Report ID: 17,048,046 Version: 1 Created: 25 Oct 2017

| Make: | Ford | Model: | Transit | Body Style: | Cab Chassis | | Pass | Fail | N/A | |
|---|--------------------------|----------------------|------------------------|--------------------|----------------------|------------------------------|--------------|---------|------------|--|
| Year: | 2,013 | Registration: | HBK481 | Reg Expiry: | 26 Dec 2017 | Engine | 1 | 1 | | |
| WoF Expiry: | | Odometer: | 102,740 Kms | Good No: | 17048046 | Oil level | ~ | | | |
| VIN: | WF0FXXTTFFCL37182 | Next Service: | 109000 | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and tl | his can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Key: | s sc | -0 | S D | | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | Transmission | | | |
| D = dent R = rust | | | | | | Operation | ~ | | | |
| PT = paint defect | | | | | | Noise | ~ | | | |
| C = crack | | | | | | Clutch | | ~ | | |
| P = pin dent | | | | | | CV joints | ~ | | | |
| * = decals SC 99 | | | | | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | | |
| W = significant scuffs S SC S D | | | | | | Performance | ~ | | | |
| Deduction | | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | | |
| body inspection comments | | | | | | Tyres (lowest observed tread | d depth | of tyre | es) | |
| Light fixture attached to roof Right rear taillight cracked | | | | | | Left front | | | | |
| | | | | | | Right front | | 5 | mm | |
| | | | | | | Left rear | | 3 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | | 3 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| Shock absorbers | | | | | | ~ | | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | Operation 🖌 | | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats Average | | | | | | Head lights | ~ | | | |
| | A. 1978 810 | | | | | Tail lights | | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | | |
| | | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | ~ | | | |
| General Comments | | | | | | Window winder RL | | | ~ | |
| Clutch pedal takes high | | | | | | Window winder RR | | | V | |
| | | | | | | Rear view mirrors | ~ | | - | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 2 | I | I | |
| Road Conditions During Test Drive: Drv | | | | | | Central locking | 2 V | | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | - | | ~ | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ | |
| L | - | • | | | | | | | _ * | |
| Inspected by: John Lindsay Date: 25 Oct 2017 | | | | | | | | | | |
| | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: