

Report ID: 17,050,444 Version: 2 13 Dec 2017 Created:

| Make: | Ford | Model: | Territory | Body Style: | SUV | | Pass | Fail | N/A | |
|--|--------------------------|----------------------|------------------------|-------------------|----------------------|------------------------------|--------------|----------|-----|--|
| Year: | 2,005 | Registration: | EER681 | Reg Expiry: | 30 Jun 2018 | Engine | I | <u> </u> | I | |
| WoF Expiry: | 20 Nov 2018 | Odometer: | 151,198 Kms | Good No: | 17050444 | Oil level | ~ | | | |
| VIN: | 6FPAAAJGAT4T90298 | Next Service: | 161100 | Service Histor | V: No | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismontled or | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional c | harge. | Coolant condition | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Key: | s sc | -0 | S SC S SC | | S P SC | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | Fransmission | | | |
| D = dent R = rust | | | | | | Operation | ~ | | | |
| R = rust PT = paint defe | | | | \prod | | Noise | ~ | | | |
| C = crack | | | | | SC | Clutch | | | ~ | |
| P = pin dent | HID | | | | 74114 | CV joints | ~ | | - | |
| * = decals | ssc 919 | | | -No- | ALC S | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | I | |
| W = significant scuffs D S P SC S P SC S D S D | | | | | | Performance | ~ | | | |
| Dodulac | | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | | |
| Body inspection Comments | | | | | | Tyres (lowest observed tread | depth | of tyre | es) | |
| Minor spider rust on the roof , | | | | | | | | | mm | |
| | | | | | | Right front | | | mm | |
| | | | | | | Left rear | - | | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5 mm | | | |
| Conditions During Body Inspection: Dry | | | | | | Spare | Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | Operation | | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats | drivers sea | it ripped,wear an | d tear , | | | Head lights | ~ | | | |
| | woarandt | ear,minor stains | | | | Tail lights | ~ | | | |
| Carpets | wear and t | | 1 | | | Indicators | ~ | | | |
| Panels | bits missin | g off doors,and s | seats,small rips, | | | Dashboard warning lights | ~ | | | |
| | ورجا معط امرا | top of dash | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | rd | top of dash , | | | | Window winder FL | ~ | | | |
| | 1 | | | | | Window winder FR | ~ | | | |
| General Comments | | | | | | Window winder RL | ~ | | | |
| | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 1 | | I | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | | |
| | | | | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ | |
| | | | | | | | | | | |
| Inspected by: Donovan Matara Date: 13 Dec 2017 | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: