

Report ID: 17,053,224 Version: 2 Created: 07 Feb 2018

Make:	Mazda	Model:	MPV	Body Style:	SUV		Pass	Fail	N/A
Year:	2,009	Registration:		Reg Expiry:		Engine			L
WoF Expiry:	2,005 20 Oct 2018	Odometer:	115,000 Kms	Good No:	17053224	Oil level	~		
VIN:	7AT0C11EX17214807	Next Service:	125000	Service Histor		Smoke & fumes	~		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		125000		, 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						-			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	STO	10			X	Transmission	V		
D = dent	Alt			1 - L	BID	Operation	~		<u> </u>
R = rust				10		Noise	~		
PT = paint def C = crack	ect			+		Clutch	~		~
P = pin dent	Ht	KI			JUII —	CV joints	~		~
* = decals	MIK			AL-	ETTR	Wheel bearings	-		
SC = stone chips						Wheel bearings			
W = significant scuffs									<u> </u>
		Nata				Performance	~		<u> </u>
Body Ins	pection Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake		<i>c</i> .	Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front	6	5	mm
						Right front	5	5	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension	1		
						Suspension performance	~		
Ste						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	<		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	~		
			Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
[-	•							
Inspected by: Jason Law Date: 07 Feb 2018									

I have read and understood this condition guide.

Name:

Signature: