

Report ID: 17,059,190

Version:

Engine Oil level Smoke & fumes

Noise

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 31 Oct 2017

Pass

~

~

1

1

1

V

Tyres (lowest observed tread depth of tyres)

N/A

mm

mm

mm

 mm

8

8

V

/


Yes

Fail

Make:	Toyota	Model:	Hilux	Body Style:	Utility
Year:	2,007	Registration:	DZH64	Reg Expiry:	12 Sep 2018
WoF Expiry:	10 May 2018	Odometer:	273,508 Kms	Good No:	17059190
VIN:	MR0FZ29G801700694	Next Service:	288000	Service Histor	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Inner sills need painting.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Sticker advises cambelt has been replaced but unable to read kms.

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Runs well.

Road Conditions During Test Drive: Dry

	CD (basic test only)	~				
	Number of keys	1				
	Central locking	~				
	Remote locking	~				
	Sat. Nav. (basic test only)		V			
s:	Reversing camera		V			
Date: 31 Oct 2017						
	Signature:					

Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No	Kms:	Sat. Nav. (basic test only) Reversing camera	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Inspected by: Brian Hill		Date: 31 Oct 2017	
have read and understood this condition guide.	Name:	Signature:	