

Report ID: 17,071,696 Version: 3 Created: 24 Apr 2018

Make:	Hyundai	Model:	Santa FE	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,001	Registration:	GTG724	Reg Expiry:	wagon 01 Jan 2018	Engine		, uii	
WoF Expiry:		Odometer:	156,879 Kms	Good No:	17071696	Oil level	~		1
VIN:	KMHSC81BR1U08525	Next Service:	150,075 1113	Service Histor		Smoke & fumes	~		
-	1000525				110	Performance	~		+
	port is not a warranty		с I I	<b>D</b>		Noise	~		+
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	/endor recommends	Cooling System	•		
a full mechar	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		1
						Performance	~		
Key:	S	-0	S S		SP	Radiator / Hoses (visual)	~		+
S = scratch	Re	AU			The	Transmission	•		
D = dent				1n-	S PT	Operation	~		1
R = rust PT = paint def				$\prod$	JHIH	Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		+
* = decals	s 916			-NL	ETTPS-	Wheel bearings	~		+
SC = stone chips						Brakes			
W = significant scuffs						Performance 🖌			
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftyre	 es)
LH wing mirror not working									
						Right front		+ 5	mm
						Left rear		р 7	mm
						Right rear		/ 7	mm
Conditions During Body Inspection: Wet						Spare	· ·		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	ring and engine oil leak	•				Suspension performance	~		1
i owei stee									
						Steering performance Shock absorbers	~		
							~		
						Air Conditioning / Heater			T
Interior Comments						Operation Electrical / Accessories	~		
	Average					Head lights			T
Seats							~		
Carpets	Good					Tail lights Indicators	<b>v</b>		
	Average						<b>/</b>		
Panels						Dashboard warning lights	<b>v</b>		+
Dashboa	rd Good					Wipers (front & rear)	<b>/</b>		
						Window winder FL	~		
General (	omments					Window winder FR	~		
General Comments Knocking noise from front						Window winder RL	~		+
						Window winder RR	~		<u> </u>
						Rear view mirrors		~	
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		T
Road Con	ditions During Tes	t Drive:	Dry			Central locking		~	─
Engine Ti	ming Mechanism	Cambal				Remote locking			~
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 66.481						Sat. Nav. (basic test only)			~
LVIGENCE		спені. ү	'es	Kms: 66	,481	Reversing camera			~
Inspecte	d by: Bobby Zhong					Date: 24 Apr 20	18		
peete						2444. 21710120	-		
I have read	and understood th	is condition o	juide. Name: .			Signature:			