

Report ID: 17,072,253 Version: 1 17 Nov 2017 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2,007	Registration:	EZH374	Reg Expiry:	12 Nov 2017	Engine			
WoF Expiry:	24 Apr 2018	Odometer:	207,617 Kms	Good No:	17072253	Oil level	~		
VIN:	6FPAAAJGAT7L84987	Next Service:	212000	Service Histor		Smoke & fumes	~		
			212000			Performance	~		
	port is not a warranty		с I I	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc	-0	S PT SC S PT P S		S D PT	Radiator / Hoses (visual)	~		
S = scratch	Se	20		10c	X	Transmission	v		
D = dent	s sc			1 - L	BID	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect M			+	S PT SC	Clutch	~		
P = pin dent	Ho	KI			JUII ——	CV joints	~		~
* = decals	SDSC PR			AL-		Wheel bearings	-		
SC = stone chips						Wheel bearings			
W = significant scuffs S SC S P T S SP SC									
	5.50	Nata				Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		,
RF headlight moisture inside ,clear coat coming off roof,A pillars,RF door,RR door,RR guard,LF door,tint coming off tail gate window ,stone chip in the windscreen ,						Tyres (lowest observed tread depth of tyres)			
coming off	tall gate window ,stone	chip in the wind	iscreen ,			Left front		7	mm
						Right front		7	mm
						Left rear	:	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments wear and tear,worn ,						Electrical / Accessories			
Seats	wear and t	tear,worn ,				Head lights	~		
Carpota	wear and	tear,minor stains	,			Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
	2		UT y			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
<u> </u>								1	
Inspected by: Donovan Matara Date: 17 Nov 2017									

I have read and understood this condition guide.

Name:

Signature: