

Report ID: 17,086,254 Version: 5 18 Dec 2018 Created:

| Make: | Chrysler | Model: | 300C | Body Style: | Sedan | | Pass | Fail | N/A |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------|------------------------|---------------------------------------|----------------------|----------------------------------------------|----------|------|----------|
| Year: | 2005 | Registration: | LDW619 | Reg Expiry: | 15 Nov 2018 | Engine | I | | 1 |
| WoF Expiry: | 17 Dec 2019 | Odometer: | 69,455 Kms | Good No: | 17086254 | Oil level | ~ | | |
| VIN: | 1C3H9E3G16Y119320 | Next Service: | 79,451 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismontled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | v | | |
| | | | | | S | Performance | ~ | | |
| Key: | S | -0 | S S | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | s dla | | | TIN | | Operation | ~ | | |
| R = rust PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | + | S S | Clutch | - | | ~ |
| P = pin dent | -110 | | | | 게 | CV joints | | | ~ |
| * = decals | s 916 | | | - Jul | ELD's | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance | ~ | | |
| Deskulation | | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | L 2s) |
| Roof top trims came out FR door outer handle insecure | | | | | | | | | mm |
| | | | | | | Right front | 6 | | mm |
| | | | | | | Left rear | 5 | | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | - | 6 m | |
| Conditions During Body inspection. Wet | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | 1 |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | Avelage | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | <u> </u> |
| | , Good | | | | | Wipers (front & rear) | ~ | | + |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | <u> </u> |
| | 1 | | | | | Window winder FR | ~ | | <u> </u> |
| General Comments | | | | | | Window winder RL | ~ | | <u> </u> |
| | | | | | | Window winder RR | ~ | | <u> </u> |
| | | | | | | Rear view mirrors | ~ | | + |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> |
| | | | | | | CD (basic test only) | ~ | | + |
| | | | | | | Number of keys | 1 | | L |
| Road Con | ditions During Test | t Drive: | Wet | |] | Central locking | ~ | | |
| | | | | | | Remote locking | | | ~ |
| Engine Tir | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | | | | 1 |
| Inspected by: Mathew Varghese Date: 18 Dec 2018 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: