

Report ID: 17,086,998 Version: 1 20 Dec 2017 Created:

Make:	BMW	Model:	5251	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,003	Registration:	FPN348	Reg Expiry:	14 Oct 2018	Engine	1	I	
WoF Expiry:	13 Dec 2018	Odometer:	166,318 Kms	Good No:	17086998	Oil level	~		
VIN:	WBADS42010BZ4276{	Next Service:	176000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SPSC	-0	S P SC S P SC	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	FILL S	Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				$+ \vee$	SC	Clutch			~
P = pin dent					게비	CV joints	~		
* = decals	ssc 916			- NL	HIP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs P SC S SC S SC S SC S D SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	oftvre	
								mm	
Rig						Right front		, 7	 mm
						Left rear		/ 7	mm
Condition		a a ati a m.				Right rear			 mm
Conditions During Body Inspection: Dry						Right rear 7 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
		·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Banala	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
<u>Gen</u> eral C	<u>Comments</u>					Window winder RL	~		
Stereo works just not picking up stations properly ,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	-	~	
						CD (basic test only)		•	~
						Number of keys	2		-
							2 1		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•								-
Inspected by: Donovan Matara Date: 20 Dec 2017									

I have read and understood this condition guide.

Name:

Signature: