

## **Basic Vehicle Condition Guide**

Report ID: 17,101,014


Version:

Created: 11 Jan 2018

Make: Model: Subaru **Body Style:** Wagon Legacy Year: 2,012 Registration: Reg Expiry: 20 Feb 2018 **GME350** WoF Expiry: **Odometer: Good No:** 23 Aug 2018 17101014 161,134 Kms VIN: JF1BR9K92CG036272 **Next Service:** 166000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Decal removal damage RH side,

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments	<u>S</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

Pass	Fail	N/A
~		
~		
~		
~		
-	<u> </u>	1
~		
·		
<u></u>		
~		
1/		
+		<b>-</b>
./		
.,		
.,		
-		
<b>/</b>	- 6 ·	
1		
	3	mm
	3	mm
1 -	3	mm
-		
	3	mm
		mm
	3	mm
V V V	3	mm
V V V	3	mm
V V V V V	3	mm
V V V V V	3	mm
V V V V V	3	mm
V V V V V	3	mm
V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
V V V V V V V V V V V V V V V V V V V	3	mm
	V V V V V	v

I have read and understood this condition guide.

Donovan Matara

Name: .....

Signature: .....

11 Jan 2018

Date: