

Report ID: 17,104,444 Version: 4 22 Feb 2018 Created:

Make:	Subaru	Model:	Levorg	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2,015	Registration:	· · ·	Reg Expiry:		Engine	I	I	L	
WoF Expiry:	30 Nov 2018	Odometer:	97,165 Kms	Good No:	17104444	Oil level	~			
VIN:	7AT0GF22X17030380	Next Service:		Service Histor		Smoke & fumes	~			
						Performance	~			
	port is not a warranty		c 1 11	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.										
						Coolant condition	~			
						Performance	~			
Key:		$-\infty$				Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	- Alle			1n-	EID ~	Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint defects C = crack	ect M			+		Clutch	~			
P = pin dent	LHC				JUII —	CV joints			~	
* = decals	MIR			AL-		Wheel bearings	~			
SC = stone chips							5			
W = significant scuffs						Brakes				
						Performance	~			
Body Insp	pection Comments	Note: som	e defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	 ✓ 		Ļ	
						Tyres (lowest observed tread depth of tyres)				
						Left front	4.0 mm		mm	
						Right front	4	.0	mm	
						Left rear	4	.0	mm	
Conditions During Body Inspection: Wet						Right rear	4.0 mm			
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Compete	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected by: Jason Law Date: 20 Feb 2018										

I have read and understood this condition guide.

Name:

Signature: