

Report ID: 17,105,853 Version: 1 Created: 04 Dec 2017

Make:	Hyundai	Model:	Accent	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,001	<b>Registration:</b>	ZY6937	<b>Reg Expiry:</b>	01 Jan 2018	Engine	1	I	
WoF Expiry:	17 Feb 2018	Odometer:	293,871 Kms	Good No:	17105853	Oil level	~		
VIN:	KMHCG51FR1U09922	Next Service:	not known.	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	r an additional C	.narge.	Coolant condition	~		
	s W		PT PT		SC	Performance	~		
Key: 5 W PI PI V SC						Radiator / Hoses (visual)	~		
						Transmission			
B = cent R = rust $W$ $A$ $A$ $C$ $W$ $C$ $W$						Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack					D PT	Clutch	~		
P = pin dent	DSC DIC				~HHL	CV joints	~		
* = decals DSC SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	W	$\sim$	PT SC	W		Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Stone chips and wiper mark front screen. No parcel shelf.						Tyres (lowest observed tread depth of tyres)			
						Left front	:	5	mm
						Right front		3	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear 4		4	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	, weitige					Head lights	~		
Carpets	Average					Tail lights	~		
	Good					Indicators	~		<b> </b>
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
General Comments Runs ok.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking		~	
Engine Timing Mechanism: Cambelt						Remote locking			~
Evidence of Cam Belt Replacement: Yes Kms: 65,000						Sat. Nav. (basic test only)			~
		Y	C3		0,000	Reversing camera			~
Inspected by: Brian Hill Date: 04 Dec 2017									

I have read and understood this condition guide.

Name: .....

Signature: .....