

Basic Vehicle Condition Guide

Report ID: 17,111,673


Version:

Created: 12 Jan 2018

Make: Model: Hiace **Body Style:** Toyota Van Year: Registration: Reg Expiry: 2,012 **GNH373** 03 Jan 2018 **WoF Expiry: Odometer:** 29 Dec 2018 **Good No:** 130,459 Kms 17111673 VIN: JTFHT02PX00098689 **Next Service:** 120000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

_	_
Conoral	Comments
General	COMMENTS

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No

Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>y y</i>		
Performance	~		
Noise	~		
Cooling System	•		•
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	8		mm
Right front	8		mm
Left rear	5		mm
Right rear	4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3	l	-
<u> </u>			
Central locking	~		
Remote locking			

Inspected by: Donovan Matara Date

I have read and understood this condition guide.

Name:

Signature:

12 Jan 2018

1

Reversing camera