

Basic Vehicle Condition Guide

Report ID: 17,113,662


Version: 1

Created: 07 Dec 2017

Make: Model: Subaru **Body Style:** Sedan Legacy Year: 2,012 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 06 Dec 2018 96,930 Kms 17113662 VIN: 7AT0GF0BX17004237 **Next Service:** 106920 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 07 Dec 2017

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System		-	1
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	V		
Transmission	ı		1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		6	mm
Right front	6		mm
Left rear	5		mm
Right rear	4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			•
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR			
Rear view mirrors	\(\times \)		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: