

Report ID: 17,113,966 Version: 1 Created: 07 Dec 2017

Make:	Daihatsu	Model:	Sirion	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,005	<b>Registration:</b>	DAH521	<b>Reg Expiry:</b>	25 Dec 2017	Engine			
WoF Expiry:	07 Apr 2018	Odometer:	64,090 Kms	Good No:	17113966	Oil level	~		
VIN:	JDAM301S001018484	Next Service:	77800	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	r an additional o	narge.	Coolant condition	~		
			SC SC		SC	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
R = rust	scw			210		Operation	~		
PT = paint defe	ect NP				11111	Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	sc de				74116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	W					Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Stone chips front screen.						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear		4	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	iu l					Window winder FL	~		
	-					Window winder FR	~		
General Comments Nice tidy car runs well.						Window winder RL	~		
INICE TIDY Ca	r runs well.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
-	ming Mechanism:	Timing (		14		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 07 Dec 2017									

I have read and understood this condition guide.

Name: .....

Signature: .....