

Report ID: 17,114,703 Version: 2 08 Dec 2017 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2,014	Registration:	HMU881	Reg Expiry:	01 Feb 2018	Engine			
WoF Expiry:	27 Jun 2018	Odometer:	26,445 Kms	Good No:	17114703	Oil level	~		
VIN:	MR0EU19G106002628	Next Service:	35000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	r an additional o	charge.	Coolant condition	~		
			S SW		S	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	Transmission		
R = rust	sc			210		Operation	~		
PT = paint def	ect NP				101/1	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints			~
* = decals	sc s 916			Tool .	ELD'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = signincan	W		SC P PT S SC		S	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	6.0 mr		
						Right front	7.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good.						Suspension performance 🖌			
						Steering performance	~		
		Shock absorbers	~						
						Air Conditioning / Heater	11		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Runs well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Brian Hill Date: 07 Dec 2017									

I have read and understood this condition guide.

Name:

Signature: