

Report ID: 17,116,479 Version: 1 Created: 09 Dec 2017

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,015	Registration:		Reg Expiry:		Engine	1	1	1
WoF Expiry:		Odometer:	69,763 Kms	Good No:	17116479	Oil level	~		
VIN:	7AT0GK0CX17361261	Next Service:	79760	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				210		Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	- Alt	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
		e				Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
					Left front	6 mm		mm	
						Right front	6	5	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
					Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashhaa	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jason Law Date: 09 Dec 2017									

I have read and understood this condition guide.

Name:

Signature: