

Report ID: 17,119,853 Version: 1 13 Dec 2017 Created:

Make: Holden Model: Captiva 5	Body Style: SUV		Pass	Fail	N/A
Year: 2,015 Registration: HWM923	<b>Reg Expiry:</b> 08 Jan 2018	Engine			1
<b>WoF Expiry:</b> 09 Jan 2018 <b>Odometer:</b> 109,614 Kms	<b>Good No:</b> 17119853	Oil level	~		
VIN: KL3DD2669FB013958 Next Service: 119331	Service History: Yes	Smoke & fumes	~		
		Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and n	nileage. Parts have not been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to	50km/h from cold. The Vendor recommends	Cooling System			1
a full mechanical inspection prior to purchase and this can be arra	iged for an additional charge.	Coolant condition	~		
Key: SC		Performance	~		
Key: S = scratch		Radiator / Hoses (visual)	~		
D = dent		Transmission			
R=rust W AR		Operation	~		
PT = paint defect		Noise	~		
C = crack	sc	Clutch			~
P = pin dent		CV joints	~		
* = decals SC = stone chips		Wheel bearings	~		
W = significant scuffs	Brakes				
		Performance	~		
Body Inspection Comments Note: some defects & ble	mishes may not be displayed in the diagram	Hand Brake	~		
Stone chips front screen. Dent right rear inner wheel arch. Drivers seatbelt frayed.		Tyres (lowest observed tread depth of tyres)			es)
		Left front	7	7	mm
		Right front	7	7	mm
		Left rear	7	7	mm
Conditions During Body Inspection: Dry		Right rear	7	7	mm
		Spare	Yes		
Under Carriage & Under Bonnet Inspection Commen	<u>ts</u>	Suspension			
Good.		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	~		
		Air Conditioning / Heater			
Interior Comments		Operation	~		
Interior Comments Good		Electrical / Accessories			
Seats		Head lights	~		
Carpets Good		Tail lights	~		
		Indicators	~		
Panels		Dashboard warning lights	~		
Dashboard Good		Wipers (front & rear)	~		
		Window winder FL	~		
General Comments		Window winder FR	~		
Runs well.		Window winder RL	~		
		Window winder RR	~		
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)	~		
		Number of keys	2		
Road Conditions During Test Drive: Dry		Central locking	~		
Engine Timing Mechanism: Timing Chain		Remote locking	~		
	L. Kmc	Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicab	le Kms:	Reversing camera			~
Inspected by: Brian Hill Date: 13 Dec 2017					

I have read and understood this condition guide.

Name: .....

Signature: .....