

Basic Vehicle Condition Guide

Report ID: 17,122,378


Version:

Created: 18 Dec 2017

Make: Model: Ford Transit **Body Style:** Van Year: 2,013 Registration: GRY773 Reg Expiry: 03 Feb 2018 WoF Expiry: **Odometer:** 05 Feb 2018 **Good No:** 17122378 70,433 Kms VIN: WF0XXXTTFXCD18747 **Next Service:** Service History: 92,000kms Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

OK, dry.

Interior Comment	<u>s</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

Dry

General Comments

Nice driving van.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 18 Dec 2017

Name:

		Pass	Fail	N/A
Engine				
Oil level		>		
Smoke & fumes		> > >		
Performance		'		
Noise		'		
Cooling Syster	n			
Coolant cond	ition	>		
Performance		>		
Radiator / Hoses (visual)		>		
Transmission				
Operation		~		
Noise		~		
Clutch		>		
CV joints				~
Wheel bearing	gs	~		
Brakes				
Performance		~		
Hand Brake		~		
Tyres (lowest o	bserved treac	l depth	of tyre	es)
Left front		8	3	mm
Right front	Right front		 3	mm
Left rear		4		mm
Right rear		4		mm
Spare			Yes	
Suspension				
Suspension p	erformance	~		
Steering perfo	ormance	V		
Shock absorb		~		
Air Conditioni	ng / Heater			
Operation		~		
Electrical / Acc	essories			l
Head lights		V		
Tail lights				
		~		
Indicators		<i>V</i>		
Indicators Dashboard wa	arning lights	<i>V</i>		
Dashboard wa		\(\times \)		
Dashboard wa Wipers (front	& rear)	\(\times \)		
Dashboard wo Wipers (front Window wind	& rear) ler FL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Dashboard wa Wipers (front Window wind	& rear) ler FL ler FR			
Dashboard was Wipers (front Window wind Window wind Window wind	& rear) ler FL ler FR ler RL			V
Dashboard wa Wipers (front Window wind Window wind Window wind	& rear) ler FL ler FR ler RL	<i>y y</i>		<i>V</i>
Dashboard was Wipers (front Window wind Window wind Window wind Window wind Rear view mir	& rear) ler FL ler FR ler RL ler RR rors			<i>V</i>
Dashboard was Wipers (front Window wi	& rear) der FL der FR der RL der RR rors est only)	<i>y y</i>		<i>V</i>
Dashboard was Wipers (front Window wi	& rear) ler FL ler FR ler RL ler RR rors est only)	V V V V		<i>V V</i>
Dashboard was Wipers (front Window wi	& rear) ler FL ler FR ler RL ler RR rors est only) only)	<i>y y</i>		<i>V</i>
Dashboard was Wipers (front Window wind Window wind Window wind Rear view mir Radio (basic test Number of ke	& rear) der FL der FR der RL der RR rors est only) only) ys	V V V V		<i>'</i>
Dashboard with Wipers (front Window w	& rear) & rear) der FL der FR der RL der RR rors est only) only) yys g ng	V V V V		<i>V V</i>
Dashboard was Wipers (front Window wind Window wind Window wind Rear view mir Radio (basic test Number of ke	& rear) der FL der FR der RR rors est only) only) ys g ng ic test only)	V V V V		V V V

Signature: