

Basic Vehicle Condition Guide

Report ID: 17,125,278

Version: 1

Created: 04 Jan 2018


Make:SuzukiModel:SwiftBody Style:HatchbackYear:2,015Registration:Reg Expiry:

 WoF Expiry:
 12 Dec 2018
 Odometer:
 67,013 Kms
 Good No:
 17125278

 VIN:
 7AT0GK0CX17360953
 Next Service:
 76989
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tyre repair kit

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Poor | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay Date: 04 Jan 2018

| | Pass | Fail | N/A |
|------------------------------|--|---------|--------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | V | | |
| Performance | V | | |
| Noise | ~ | | |
| Cooling System | 1 | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | ļ. | l | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | 1 | | |
| Performance | V | | |
| Hand Brake | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Tyres (lowest observed tread | d denth | of tyre | 25) |
| Left front | T | - | mm |
| Right front | 6 | | mm |
| Left rear | | | mm |
| Right rear | 4 | | mm |
| Spare | 4 | | 111111 |
| Suspension | | N/A | |
| Suspension performance | | | |
| Steering performance | | | |
| Shock absorbers | | | |
| Air Conditioning / Heater | <i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i> | | |
| | | | |
| Operation | • | | |
| Electrical / Accessories | | | I |
| Head lights | <i>V</i> | | |
| Tail lights | <i>V</i> | | |
| Indicators | \(\times \) | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | V | | |
| Window winder RR | | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | 1 |

I have read and understood this condition guide.

Name:

Signature: