

Report ID: 17,128,139 Version: 2 Created: 03 Apr 2018

Make:	Subaru	Model:	Forester	Body Style: SUV			Pass	Fail	N/A
Year:	2,006	Registration:		Reg Expiry:		Engine			
WoF Expiry:		Odometer:	94,301 Kms	Good No: 171281	39	Oil level	~		
VIN:	7AT0GF17X17105000	Next Service:	104200	Service History: No		Smoke & fumes	~		
			101200	, 110		Performance	~		
	port is not a warranty		C 1 11			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	Re	AU		10 Th		Transmission	•		
D = dent						Operation	~		<u> </u>
R = rust PT = paint defe						Noise	~		-
C = crack					-	Clutch	•		~
P = pin dent						CV joints	~		-
* = decals	616				4	Wheel bearings	~		
SC = stone chi		V A	\Box	102		Brakes	•		
W = significan	t scuffs	$- \emptyset$				Performance	~		
		Note: som	e defects & blemish	es may not be displayed in t	the diagram	Hand Brake	~		
Body Insp	pection Comments				ine ungruin	Tyres (lowest observed tread	-	of tyre	<u> </u>
						Right front	4		mm
						Left rear	4		mm
							4		mm
Conditions During Body Inspection: Dry									111111
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			<u> </u>
Interior Comments						Operation Electrical / Accessories			
Good						Head lights			<u> </u>
Seats						3	~		
Carpets	Good					Tail lights Indicators	レ レ		
	Good								
Panels						Dashboard warning lights Wipers (front & rear)	v		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		
							v		
General (Comments					Window winder FR Window winder RL	~		
							v		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
		~ .				Number of keys	1		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Tir	ming Mechanism:	Cambelt	-			Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
			10	13113.		Reversing camera			~
Inspected by: Jason Law Date: 03 Apr 2018									

I have read and understood this condition guide.

Name:

Signature: