

## **Basic Vehicle Condition Guide**

Report ID: 17,129,553

Version: 2


Created: 22 Jun 2018

Pass Fail N/A

Make: Model: Dodge Caliber **Body Style:** Hatchback Year: 2,008 Registration: ENG155 Reg Expiry: 23 Mar 2018 **WoF Expiry: Odometer: Good No:** 17129553 22 May 2018 113,623 Kms VIN: 1B3H348A57D196861 **Next Service: Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\( \triangle \)		
Noise	~		
Cooling System	•		•
Coolant condition	~		
Performance	<b>V</b>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints	\( \times \)		
Wheel bearings	~		
Brakes		1	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d dept	h of tyr	es)
Left front		5.0	mm
Right front	3.8		mm
Left rear			mm
Right rear			mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		-	-
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V		
Window winder RL	~		+
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	v		+
Number of keys	1	1	1
Central locking	· /		Т
Remote locking	·		+
Sat. Nav. (basic test only)			\ <u>\</u>
	1		

Reversing camera

Signature: .....

Inspected by: Jason Young Date: 11 Jan 2018

Name: .....