

Basic Vehicle Condition Guide

Report ID: 17,140,141

Version: 1

Created: 12 Jan 2018

Pass


N/A

Fail

Make: Model: **Body Style:** Toyota Hiace Van Year: Registration: **Reg Expiry:** 2,000 ZF2089 26 Sep 2018 WoF Expiry: **Odometer: Good No:** 27 Jul 2018 191,193 Kms 17140141 VIN: **Next Service: Service History:** JT721LHA301043190 195000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	
Seats	drivers seat ripped,worn,wear and tear,stains ,
Carpets	drivers floor ripped, worn wear and tear ,
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Engine Oil level Smoke & fumes 1 Performance / Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch J CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front mm 1.5 Left rear 1.5 mm Right rear mm 4 Spare No Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR 1 Rear view mirrors / Radio (basic test only) CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only)

I have read and understood this condition guide.

Donovan Matara

Name:

Signature:

12 Jan 2018

Reversing camera

Date: