

Basic Vehicle Condition Guide

Report ID: 17,144,651


Version:

Created: 19 Jan 2018

Make: Model: Honda CRV **Body Style:** Wagon Year: 1,996 Registration: CWR742 Reg Expiry: 02 Jan 2018 WoF Expiry: **Odometer: Good No:** 17144651 289,033 Kms VIN: 7A88G7H0705088268 **Next Service:** Service History: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Bonnet needs paint oxidised,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	l depth	of tyre	,e) 	
Left front 6 mm				
Right front	_		mm	
Left rear	4		mm	
Right rear	6 2		mm	
	-			
Spare Yes Suspension				
Suspension performance				
Steering performance	./			
Shock absorbers	./			
	•			
Air Conditioning / Heater				
Operation Electrical / Accessories				
Head lights	<i>V</i>			
Tail lights	-			
Indicators	•			
Dashboard warning lights	VVV			
Wipers (front & rear)	•			
Window winder FL	~			
Window winder FR	'			
Window winder RL	•			
Window winder RR	V			
Rear view mirrors				
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2		1	
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			'	

Signature:

19 Jan 2018 Inspected by: Donovan Matara

Name: