

I have read and understood this condition guide.

Report ID: 17,145,652 Version: 1 15 Jan 2018 Created:

Signature:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,011	Registration:	HZE206	Reg Expiry:	10 Mar 2018	Engine			
WoF Expiry:	09 Feb 2018	Odometer:	105,732 Kms	Good No:	17145652	Oil level	~		
VIN:	WVWZZZ1KZBW17604	Next Service:	116000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S P SC S P SC	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent					세비	CV joints	~		•
* = decals	616			-NL	ELLEN	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S S P						Performance			
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
	pection Comments	10000.3011	le delects & blemisnes	inay not be disp	ayed in the diagram		•	ofture))
Front bumper needs alignment ,					Tyres (lowest observed tread depth of tyres) Left front 6				
								5	mm
						Right front		3	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
		ince inspectie	<u>in comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Good Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
	iiu					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L									
Inspected by: Donovan Matara Date: 15 Jan 2018									

Name: