

Report ID: 17,146,522 Version: 2 18 Jan 2018 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HKW909	Reg Expiry:	29 Jan 2018	Engine			L
WoF Expiry:	19 May 2018	Odometer:	195,665 Kms	Good No:	17146522	Oil level	~		
VIN:	KMHST81XSEU277354	Next Service:	203170	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	ansmission		
D = dent R = rust	w dla			715	HIL	Operation	~		
PT = paint defe		F		$\left(\left \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sc 916			-July		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant						Performance	~		
Podylocr	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Stone chips front screen.						Tyres (lowest observed tread depth of tyres)			2S)
						Left front 6.0 r			mm
						Right front	6.	.0	mm
						Left rear	6.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Runs well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 04 Jap 2019									
Inspected by: Brian Hill Date: 04 Jan 2018									

I have read and understood this condition guide.

Name:

Signature: