

Report ID: 17,148,179 Version: 1 30 Jan 2018 Created:

Make:	Mitsubishi	Model:	Airtrek	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,001	Registration:	CHF669	Reg Expiry:	14 Jul 2018	Engine	1		
WoF Expiry:	31 May 2018	Odometer:	243,323 Kms	Good No:	17148179	Oil level	~		
VIN:	7A8CJ3F0704004464	Next Service:	250,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC SSCW	-01-	SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack				+	P W	Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals SRSC 999 SPW						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S P W S P W S S S						Performance	~		
Dedular		Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
Body inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
Stone chipping on front windscreen								mm	
						Right front	6.		mm
						Left rear	4.		mm
Conditions During Body Inspection: Wet						Right rear	3.		mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil w	eep around engine sum	np.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
Vinyl panel on base of drivers seat has cracking all over it.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	1
Road Conditions During Test Drive: Wet						Central locking	~		
Road Conditions During Test Drive: Wet						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 22	27,700	Reversing camera			~
								1	· ·
Inspected by: Jason Young Date: 17 Jan 2018									

I have read and understood this condition guide.

Name:

Signature: