

Basic Vehicle Condition Guide

Report ID: 17,149,908


Version: 1

Created: 11 Jan 2018

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2,016 Registration: JWZ354 Reg Expiry: 27 Dec 2017 Good No: **WoF Expiry: Odometer:** 28 Jun 2019 17149908 288,893 Kms VIN: MMAJYKK10GH02897 **Next Service: Service History:** 30,000kms Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Tidy & dry.

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Very tidy, nice driving d/cab ute.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 11 Jan 2018

Name:

Engine Oil level	Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	\(\times \)		
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front K V CV V V V V V V V V V V V V V V V V V V	Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	\(\times \)		
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Fransmission Operation Noise Clutch CV joints Wheel bearings Brakes			
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Fransmission Operation Noise Clutch CV joints Wheel bearings Brakes			
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes			· ·
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Coolant condition Performance Radiator / Hoses (visual) Fransmission Operation Noise Clutch CV joints Wheel bearings Brakes	\(\times \)		
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front Radiator / Hoses (visual)	Performance Radiator / Hoses (visual) Fransmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V V V		· ·
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Radiator / Hoses (visual) Fransmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V V		· ·
Transmission Operation Noise Clutch CV joints Wheel bearings Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Operation Noise Clutch CV joints Wheel bearings Brakes	V V		·
Operation Noise Clutch CV joints Wheel bearings Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Operation Noise Clutch CV joints Wheel bearings Brakes	<i>V</i>		·
Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Noise Clutch CV joints Wheel bearings Brakes	\(\times \)		<i>'</i>
Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Clutch CV joints Wheel bearings Brakes	<i>V</i>		V
CV joints Wheel bearings Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	CV joints Wheel bearings Brakes	v		~
Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Wheel bearings Brakes	V		_
Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Brakes	~		~
Performance Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm		1 '		
Hand Brake Tyres (lowest observed tread depth of tyres) Left front Right front 6 mm	Performance	•		
Tyres (lowest observed tread depth of tyres) Left front 6 mm Right front 6 mm		~		
Left front 6 mm Right front 6 mm	Hand Brake	~		
Right front 6 mm	Tyres (lowest observed tread	depth	of tyre	es)
1.6	Left front		б	mm
Left rear 6 mm	Right front	6		mm
	Left rear	6		mm
Right rear 6 mm	Right rear	6		mm
Spare Yes	Spare		Yes	
Suspension	Suspension			
Suspension performance 🗸	Suspension performance	~		
Suspension performance Steering performance Shock absorbers	Steering performance	~		
Shock absorbers 🗸	Shock absorbers	~		
Air Conditioning / Heater	Air Conditioning / Heater			
Operation 🗸	Operation	~		
Electrical / Accessories	Electrical / Accessories			
Head lights 🗸	Head lights	~		
Tail lights 🗸	Tail lights	~		
Indicators 🗸	Indicators	~		
Dashboard warning lights 🗸	Dashboard warning lights	~		
Wipers (front & rear)	Wipers (front & rear)	~		
Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors		~		
Window winder FR 🗸		~		
Window winder RL 🗸	Window winder RL	~		
Window winder RR	Window winder RR	~		
Rear view mirrors	Rear view mirrors	~		
Radio (basic test only)	Radio (basic test only)	~		
CD (basic test only)	·	~		
Number of keys 2	Number of keys	2	1	
Central locking 🗸	Central locking	~		
Remote locking 🗸	Remote locking	~		
Sat. Nav. (basic test only)	Sat. Nav. (basic test only)			~
Reversing camera		V		1

Signature: