

Basic Vehicle Condition Guide

Report ID: 17,154,825

Pass

Version:

Created: 20 Feb 2018


Fail

N/A

Make: Model: Subaru **Body Style:** Wagon Legacy Year: 2,004 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 11 Jan 2019 98,650 Kms 17154825 VIN: 7AT0GF0BX17019412 **Next Service:** 108639 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Bobby Zhong

Kms:

Engine				
Oil level	~			
Smoke & fumes	~			
Performance	V V			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	V			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	s)	
Left front		4	mm	
Right front	4		mm	
Left rear	4		mm	
Right rear	4		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	V V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	VVV			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	\(\times \)			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	<u>/</u>			
Remote locking	<i>V</i>			
Sat. Nav. (basic test only)			V	
Reversing camera			<i>y</i>	
eversing curriera	1	1	· •	

I have read and understood this condition guide.

Name:

Signature:

20 Feb 2018

Date: