

Report ID: 17,155,698 Version: 2 Created: 17 Jan 2018

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2,008	Registration:	JCY343	Reg Expiry:	25 Sep 2018	Engine			
WoF Expiry:		Odometer:	209,807 Kms	Good No:	17155698	Oil level	~		
VIN:	MM0UNY0E40080740	Next Service:	,	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for any and milago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and tl	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:	sc	-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent	w 6/6			TIN	Ell c	Operation	~		
R = rust PT = paint def				í In	JHH	Noise	~		
C = crack				+	SC SC	Clutch	~		
P = pin dent					ᅰЦ	CV joints	~		
* = decals	sc 916		<u> </u>	- AL	ETP D	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC SC SC						Performance	~		
		Note: son	ne defects & blemisher	may not be disp		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre	l
Inner sills need painting. Minor stone chips front screen.									mm
						Right front			 mm
						Left rear	3.		mm
Con alitica	n a Duurin ar Da du ha ar	t	_			Right rear	5.		mm
Conditions During Body Inspection: Dry						Spare	1.0		
Under Carriage & Under Bonnet Inspection Comments						Suspension Yes			
Good.						Suspension performance	~		1
0000						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
		Operation	~		1				
Interior Comments						Electrical / Accessories	V		
Contro	Average					Head lights	~		T
Seats						Tail lights	~		
Carpets	Average						~		
	Good								
Panels						Dashboard warning lights	~		
Dashboa	ard Good					Wipers (front & rear) Window winder FL	v		
							~		
General (omments					Window winder FR	~		
General Comments Runs well.						Window winder RL			~
Roof lining dirty						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism	Cambal	+			Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Lvidence		ement. N	10	NH 5 .		Reversing camera			~
Inspected by: Brian Hill Date: 16 Jan 2018									
I have read and understood this condition guide. Name:									