

Report ID: 17,157,157 Version: 2 Created: 05 Feb 2018

Make:	Toyota	Model:	Landcruiser Prado	Body Style:	SUV][Pass	Fail	N/A	
Year:	2,003	Registration:	BDT133	Reg Expiry:	31 Mar 2018		Engine		•	•	
WoF Expiry:	23 Nov 2018	Odometer:	329,450 Kms	Good No:	17157157		Oil level		~		
VIN:	JTEBU29JX00002967	Next Service:	336953	Service Histor	y: No		Smoke & fumes	~			
						il	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional of	charge.	J	Coolant condition		~		
						1	Performance	~			
Key:	IS SC	$-\infty$	S SC S	-(0)-	s		Radiator / Hoses (visual)	~			
S = scratch							Transmission				
D = dent R = rust SC							Operation	~			
PT = paint defe	ect NP	F I		$\left[\left(\right) \right]$			Noise	~			
C = crack							Clutch			~	
P = pin dent							CV joints	~			
* = decals	sc 916			-No-			Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs SC S S S S							Performance	~			
Dodula	action Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram		Hand Brake	~			
Body Inspection Comments Trim on drivers door loose							Tyres (lowest observed tread	l depth	of tyre	es)	
Boot around 4/2wd selector broken clips							Left front 6.0 m				
							Right front		.0	mm	
							Left rear).0	mm	
Condition	as During Body Ins	nection:				۱İ	Right rear		.0	mm	
Conditions During Body Inspection: Dry						1	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
Tidy and dry							Suspension performance	~			
							Steering performance	V			
							Shock absorbers	· ·			
							Air Conditioning / Heater	•			
						1	Operation	~			
Interior Comments							Electrical / Accessories				
Seats	Drivers se	at worn					Head lights	~			
							Tail lights	~			
Carpets	Average						Indicators	• •			
Panels	Average						Dashboard warning lights	~			
							Wipers (front & rear)	v v			
Dashboa	rd Average						Window winder FL	• •			
	I] [Window winder FR	~			
General Comments						1	Window winder RL	~			
Runs and drives ok							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	v v			
							Number of keys				
Pood Conditions During Test Driver							Central locking	1			
Road Conditions During Test Drive: Dry							-	-			
Engine Timing Mechanism: Timing Chain							Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only) Reversing camera			v	
										~	
Inspected by: Murray Craig Date: 16 Jan 2018											

I have read and understood this condition guide.

Name:

Signature: