

Report ID: 17,211,668 Version: 2 13 Feb 2018 Created:

Make:	Subaru	Model:	Forester	Body Style:	SUV	1		Pass	Fail	N/A	
Year:	2,007	Registration:	EGK244	Reg Expiry:	18 Jun 2018		Engine				
WoF Expiry:	22 Feb 2019	Odometer:	199,295 Kms	Good No:	17211668		Oil level	~			
VIN:	JF2SG9KR58G100632	Next Service:	206806	Service Histor	y: Yes		Smoke & fumes	~			
							Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.		Coolant condition	~			
						1	Performance	~			
Key:	SC	-0	S D P SC	-0×	sc		Radiator / Hoses (visual)	~			
S = scratch D = dent							Transmission		1		
B = aent R = rust W A A S S S							Operation	~			
PT = paint defect							Noise	~			
C = crack							Clutch			~	
P = pin dent							CV joints	~			
* = decals SC 919							Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs P SC S SC							Performance	~			
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	V			
Body Inspection Comments							Tyres (lowest observed tread depth of tyres)				
Stone chips on screen.							Left front		.0	mm	
							Right front	-	.0	mm	
							Left rear		.0	mm	
Conditions During Body Inspection: Dry						٦	Right rear		.0	mm	
Conditions During Body Inspection: Dry							Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension		103		
OK, dry.							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
L							Operation	~			
Interior Comments							Electrical / Accessories				
Seats	Average						Head lights	~			
	Average						Tail lights	~			
Carpets	Average						Indicators	· ·			
Panels	Average						Dashboard warning lights	~			
							Wipers (front & rear)	~			
Dashboa	ard Average						Window winder FL	~			
	I						Window winder FR	V			
General Comments							Window winder RL	V			
Nice driving Forester.							Window winder RR	V			
							Rear view mirrors	V			
							Radio (basic test only)	~			
							CD (basic test only)	~			
							Number of keys	1	I	1	
Road Conditions During Test Drive: Dry							Central locking	V			
			ы				Remote locking	V			
Engine Timing Mechanism: Cambelt							Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Yes Kms: 101,607							Reversing camera			~	
Inspected by: Daryll Timms Date: 17 Jan 2018											

I have read and understood this condition guide.

Name:

Signature: