

Basic Vehicle Condition Guide

Report ID: 17,263,845


Version: 1

Created: 22 Jan 2018

Make: Model: **Body Style:** SUV Ssangyong Rexton Year: 2,013 Registration: HBN37 Reg Expiry: 25 Sep 2018 **WoF Expiry: Odometer:** 21 Sep 2018 **Good No:** 17263845 115,804 Kms VIN: KPTH0B1FSDP316495 **Next Service: Service History:** 125,000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara

Created: 22 Jan 2018					
	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	V				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes		l			
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	8		mm		
Right front	9		mm		
Left rear	9		mm		
Right rear	10		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	V V V V V				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	2				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera	~				

22 Jan 2018