

Report ID: 17,264,097 Version: 1 Created: 03 Mar 2018

Make:	Nissan	Model:	Maxima	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,004	<b>Registration:</b>	BSK207	Reg Expiry:	14 Jan 2019	Engine	1	I	1
WoF Expiry:	10 Mar 2018	Odometer:	226,566 Kms	Good No:	17264097	Oil level	~		
VIN:	JN1BBUJ31A0001552	Next Service:	236,563kms	Service Histor	V: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc w	-0	S P SC W S W	-M-	<u>s w</u>	Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	S PT SC W			715	SW	Operation	~		
PT = paint defe		F I		$\left[ \left( \right) \right]$		Noise	V		
C = crack					S R SC W	Clutch			~
P = pin dent	HIG				74 <u>11</u>	CV joints	~		
* = decals	SDSCW 91			-July	<b>BID</b> SPTPW	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W S W S S S D W S W S D						Performance	~		
Rodular	action Commerts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
Left engine bay inner guard has rust developing. Rear left tyre outer edge wearing.								mm	
						Right front		.0	mm
						Left rear		.0 .9	mm
Conditions During Body Inspection: Dry						Right rear		3.0 m	
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Front brake	pads wearing low. Min	or oil leak from r	ight side of engine.			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			1
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets	Guou					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Movement in seat rail on drivers seat.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	V		
						CD (basic test only)	~		
						Number of keys	2	I	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1	1	
Inspected	d by: Jason Young					Date: 24 Feb 20	18		

I have read and understood this condition guide.

Name: .....

Signature: .....