

Report ID: 17,264,218 Version: 1 18 Jan 2018 Created:

Make:	Nissan	Model:	Cefiro	Body Style:	Sedan		Pass	Fail	N/A
Year:	1,996	Registration:	CDZ127	Reg Expiry:	25 Apr 2018	Engine		-	
WoF Expiry:		Odometer:	104,100 Kms	Good No:	17264218	Oil level	~		
VIN:	7A8DH2A0704123080	Next Service:	112000	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I н	.		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc	-0	S P SC S P SC		S P SC	Radiator / Hoses (visual)	~		
S = scratch	STO	A CO			X	Transmission	v		
D = dent	S D SC				EID S	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect III			+		Clutch	~		
P = pin dent	Htc	KI			JIII —	CV joints	~		
* = decals	s sc pp			AL-		Wheel bearings	-		
SC = stone chi	ps US	VA		1au	&	Brakes	~		
W = significant scuffs S D SC S S D S D S D SC S D									
		Nata				Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~	<u> </u>	Ļ
LF door mirror casing broken ,						Tyres (lowest observed tread depth of tyres)			
						Left front	7	,	mm
						Right front	7		mm
						Left rear	7		mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	irriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carnet	Average					Tail lights	~		
Carpets						Indicators	<		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		•
Road Conditions During Test Drive: Dry Central locki							~		
	-					Remote locking			~
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
L							L		1
Inspected by: Donovan Matara Date: 18 Jan 2018									

I have read and understood this condition guide.

Name:

Signature: