

Report ID: 17,265,917 Version: 1 23 Jan 2018 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,005	Registration:	FTK755	Reg Expiry:	08 Aug 2018	Engine	1	l	L
WoF Expiry:	29 Jan 2019	Odometer:	123,923 Kms	Good No:	17265917	Oil level	~		
VIN:	KMHEU41CR6A12892	Next Service:	due	Service History		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	s sc w	-0	S SC S		s	Radiator / Hoses (visual)	~		
S = scratch D = dent B = rurt						Transmission			
						Operation		~	
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect M			$\square \cup$		Clutch	V		~
P = pin dent	Ho				JUII —	CV joints	~		~
* = decals	s sc w			AL-	EIRS	Wheel bearings			
SC = stone chips						Wheel bearings			
W = significant scuffs S S S S S S S S S S S S S S S S S S									
		Nata				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~	6 .	
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	.0	mm
						Right front	5.0 mn		mm
						Left rear	6.0 mm		mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
Under Comiene Olle der Deursetlerne etige Commente						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dachher-	Good					Wipers (front & rear)	۲		
Dashboa	iiu					Window winder FL	~		
						Window winder FR	۲		
General C	<u>Comments</u>					Window winder RL	<		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Dion Mair Date: 22 Jan 2018									

I have read and understood this condition guide.

Name:

Signature: